

COUNTERSUNK ■ AB TYPE SELF TAPPING SCREWS

BOX QTY 100



| GAUGE | LENGTH | 1/2" | 5/8" | 3/4" | 1" | 1 1/4" | 1 1/2" | 2" | 2 1/2" | 3" | 4" | DRIVER SIZE |
|-------|--------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|-------------|
| | | 13mm | 16mm | 19mm | 25mm | 32mm | 38mm | 50mm | 63mm | 75mm | 100mm | |
| 4 | 2.9mm | RTCS04D | | RTCS04F | RTCS04G | | | | | | | T10 |
| 6 | 3.5mm | RTCS06D | RTCS06E | RTCS06F | RTCS06G | RTCS06H | RTCS06I | | | | | T15 |
| 8 | 4.2mm | RTCS08D | RTCS08E | RTCS08F | RTCS08G | RTCS08H | RTCS08I | RTCS08J | RTCS08K | | | T20 |
| 10 | 4.8mm | RTCS10D | RTCS10E | RTCS10F | RTCS10G | RTCS10H | RTCS10I | RTCS10J | RTCS10K | RTCS10L | RTCS10N | T25 |
| 12 | 5.5mm | | | | RTCS12G | RTCS12H | RTCS12I | RTCS12J | RTCS12K | RTCS12L | | T27 |
| 14 | 6.3mm | | | RTCS14F | RTCS14G | RTCS14H | RTCS14I | RTCS14J | | | | T30 |

BUTTON HEAD ■ AB TYPE SELF TAPPING SCREWS

BOX QTY 100



| GAUGE | LENGTH | 3/8" | 1/2" | 5/8" | 3/4" | 1" | 1 1/4" | 1 1/2" | 2" | 2 1/2" | 3" | DRIVER SIZE |
|-------|--------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|-------------|
| | | 9.5mm | 13mm | 16mm | 19mm | 25mm | 32mm | 38mm | 50mm | 63mm | 75mm | |
| 6 | 3.5mm | RTBS06C | RTBS06D | RTBS06E | RTBS06F | RTBS06G | | RTBS06I | | | | T10 |
| 8 | 4.2mm | RTBS08C | RTBS08D | RTBS08E | RTBS08F | RTBS08G | RTBS08H | RTBS08I | RTBS08J | | | T15 |
| 10 | 4.8mm | | RTBS10D | RTBS10E | RTBS10F | RTBS10G | RTBS10H | RTBS10I | RTBS10J | | | T25 |
| 12 | 5.5mm | | | | | RTBS12G | RTBS12H | RTBS12I | RTBS12J | RTBS12K | RTBS12L | T27 |
| 14 | 6.3mm | | | | RTBS14F | RTBS14G | RTBS14H | RTBS14I | RTBS14J | | | T30 |

COUNTERSUNK ■ METRIC MACHINE SCREWS

BOX QTY 100



| GAUGE | LENGTH | 6mm | 8mm | 10mm | 12mm | 16mm | 20mm | 25mm | 30mm | 35mm | 40mm | 50mm | 55mm | 60mm | 70mm | 80mm | DRIVER SIZE |
|-------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-------------|
| | | M3 | RTCM 0306 | RTCM 0308 | RTCM 0310 | RTCM 0312 | RTCM 0316 | RTCM 0320 | RTCM 0325 | | | | | | | | |
| M4 | RTCM 0406 | RTCM 0408 | RTCM 0410 | RTCM 0412 | RTCM 0416 | RTCM 0420 | RTCM 0425 | RTCM 0430 | | | RTCM 0440 | RTCM 0450 | | | RTCM 0470 | | T20 |
| M5 | | RTCM 0508 | RTCM 0510 | RTCM 0512 | RTCM 0516 | RTCM 0520 | RTCM 0525 | RTCM 0530 | | | RTCM 0540 | RTCM 0550 | | | | RTCM 0580 | T25 |
| M6 | | RTCM 0608 | RTCM 0610 | RTCM 0612 | RTCM 0616 | RTCM 0620 | RTCM 0625 | RTCM 0630 | | | RTCM 0640 | RTCM 0650 | | | | RTCM 0680 | T30 |
| M8 | | | | | RTCM 0816 | RTCM 0820 | RTCM 0825 | RTCM 0830 | | | RTCM 0840 | RTCM 0850 | RTCM 0855 | RTCM 0860 | | RTCM 0880 | T40 |
| M10 | | | | | | | RTCM 1025 | | RTCM 1035 | RTCM 1040 | RTCM 1050 | | | RTCM 1060 | RTCM 1080 | | T45 |

BUTTON HEAD ■ METRIC MACHINE SCREWS

BOX QTY 100



| GAUGE | LENGTH | | | | | | | | | | | | | | | | | DRIVER SIZE | | |
|-------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|----|-----------|-------------|------------|-----|
| | 6 | 8 | 10 | 12 | 16 | 20 | 25 | 30 | 35 | 40 | 50 | 55 | 60 | 65 | 70 | 75 | 80 | | 100 | |
| | mm | mm | mm | mm | | |
| M3 | RTBM 0306 | RTBM 0308 | RTBM 0310 | RTBM 0312 | RTBM 0316 | RTBM 0320 | RTBM 0325 | | | | | | | | | | | | T10 | |
| M4 | RTBM 0406 | RTBM 0408 | RTBM 0410 | RTBM 0412 | RTBM 0416 | RTBM 0420 | RTBM 0425 | RTBM 0430 | | RTBM 0440 | RTBM 0450 | | | | | | | | T20 | |
| M5 | | RTBM 0508 | RTBM 0510 | RTBM 0512 | RTBM 0516 | RTBM 0520 | RTBM 0525 | RTBM 0530 | | RTBM 0540 | RTBM 0550 | | | | | | | | T25 | |
| M6 | | RTBM 0608 | RTBM 0610 | RTBM 0612 | RTBM 0616 | RTBM 0620 | RTBM 0625 | RTBM 0630 | RTBM 0635 | RTBM 0640 | RTBM 0650 | | RTBM 0660 | | | | | RTBM 0680 | T30 | |
| M8 | | | | RTBM 0812 | RTBM 0816 | RTBM 0820 | RTBM 0825 | RTBM 0830 | RTBM 0835 | RTBM 0840 | RTBM 0850 | RTBM 0855 | RTBM 0860 | | | | RTBM 0875 | RTBM 0880 | RTBM 08100 | T40 |
| M10 | | | | | | RTBM 1020 | RTBM 1025 | RTBM 1030 | RTBM 1035 | RTBM 1040 | RTBM 1050 | | RTBM 1060 | RTBM 1065 | RTBM 1070 | | | RTBM 1080 | | T45 |

RAISED COUNTERSUNK ■ METRIC MACHINE SCREWS

BOX QTY 100



| GAUGE | LENGTH | | | | | | | | DRIVER SIZE |
|-------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-------------|
| | 12 | 20 | 25 | 30 | 35 | 40 | 50 | 75 | |
| | mm | |
| M3.5 | RTRM 3512 | RTRM 3520 | RTRM 3525 | RTRM 3530 | RTRM 3535 | RTRM 3540 | RTRM 3550 | RTRM 3575 | T10 |



DID YOU KNOW ...

• Self Tapping Screws can be substituted for Wood screws

=> Outil de pose Resitorx®

